

INTENDED USE

The Beam Clamp Brackets are suitable for supporting directly from beams. Ideal for retrospective and modification work, or where hot work is prohibited.

The bracket is attached to the beam with an M10 bolt. Threaded holes on the side and bottom are used for attaching brackets or threaded bar.

3 clamp types are available:

h: 25 mm /Ø: M6

h: 25 mm /Ø: M10

h: 35 mm /Ø: M10

INSTRUCTION FOR USE

Measure and mark the position of the beam brackets.

Hook the bracket over the flange, and tighten the tapered bolt securely.

Pressure plates are available to spread the clamping pressure area.



User Guide for Bolts:
Recommended Torque

